

# **Navajo Abandoned Uranium Mine**

## **Site Screen Report**

*This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.*

*The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.*

### **Tommy James Mine AUM Site**

**Navajo AUM Northern Region**

**Prepared by:**

**Weston Solutions, Inc.**

**Contract: W91238-06-F-0083**

**12767.063.496.1111**

**March 2010**

## **Part I Site Identification, Location and Status**

**Site Names and ID numbers as applicable**

**Mine ID:** 203

**Map ID:** N251

**CERCLIS:** NNN000908862

## Navajo Abandoned Mine Land Reclamation Program: NA-0331

**Local name / Aliases:** Fall Down Mesa; T. J. #9 Mine

### **Chapter and local area:** Round Rock Chapter

**Lat/Long:** 36.5100118827 N / -109.268569975 W

**Nearby road and highway:** Indian Route 33      **Local Post Office:** Lukachukai, AZ

**Surface Land Status: check one or more and provide ownership and contact information below**

**Tribal Trust Land**  
**Private**  
**Bureau of Land Mgmt**  
**State**

## **Public lands**

## **Tribal Fee Land**

## **Allotment**

## **Fee land**

## Subsurface Mineral Rights:

No information on subsurface mineral rights ownership was found in the EPA/AUM Database.

### **Claim and operator information:**

The mine site surface land status is classified as Tribal Trust Land. Historical documents showed the operator of the mine as Price Exploration from 1955 to 1956. No other historical ownership / lease information was identified in the EPA/AUM database.

### Number of residential structures within 200 feet of mine:

None

### Estimated volume of mine waste onsite:

## Unknown

## Part II              Summary of radiological readings

### Highest gamma radiation measurement:

15,603 counts per minute (cpm)

### Describe any other radiological measurements:


Weston was unable to access the site, due to steep grades all known paths to the site were impassible. Measurements were collected in the vicinity of the, at approximately 150' north of the site boundary. A total of 410 gamma radiation measurements were collected near the mine site, ranging from 8,116 cpm to 15,603 cpm. The measurements are represented in Figures 1 and 2.

**Background Locations**  
#1 8,250 cpm

**Average background = 8,250 cpm**

### Distribution Chart and Statistics:

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



Count:	410
Minimum:	8116.00000
Maximum:	15603.00000
Sum:	4569340.00000
Mean:	11144.73171
Median:	11036.50000
Standard Deviation:	1243.75395

### **Part III        Status of Reclamation and Mine Waste**

**The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:**

**NAMLRP Status of the mine site: Reclaimed : Yes        Waste Pile onsite : Yes**

**NAMLRP Project Number: NA-0331**

**NAMLRP Mine features: 2 Portals**

---

**The following information was obtained from field observations collected during the 2009 site screening:**

**Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.**

**Observed reclamation work and status:**

**Adits**

Unknown

**Waste Piles**

Unknown

**Pits**

Unknown

**Shafts**

Unknown

**Other Debris and Mine Features**

The site was inaccessible, therefore no other mine features were observed during the site visit.

## Part IV

### Site observations and Environs

**Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:**

**0 to 200 feet:** None

**200 feet to 0.25 mile:** None

**Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:**

**0 to 200 feet:** None

**200 feet to 0.25 mile:** None

**Levels measured around the perimeter(s) of the identified structure(s):**

None

**Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:**

**0 to 0.25 miles:** None

**0.25 miles to 4 miles:** None

**Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.**

None observed

**Known Site History: include information from interviews with Chapter officials and residents. Note information on mine ownership, type of mining operation, period of operation, known amount of production, and any other information as provided.**

Tommy James mine consists of an area of 8,347.92 m<sup>2</sup>. The mine was identified as being operational from 1955 to 1956. Historical documents showed the operator of the mine as Price Exploration from 1955 to 1956. While operational, the mine had a total reported production volume of 853 tons. No other historical information or any additional ownership / lease information was identified in the EPA/AUM database.

## **Part V            Response Action Summary**

**Site Name(s):** Tommy James        **Chapter:** Round Rock

### **Decision Criteria**

**Is there an unreclaimed waste pile at the site?** Unknown

**At what distance from the waste pile is the nearest residential structure located?** None

**At what distances from the waste pile are there potential drinking water sources?** None

**Is there a reclamation cap or sealed adit in place at the site?** Unknown

**Is the cap/seal functionally intact?** Unknown

**Is the cap/seal sufficiently degraded to create a concern about releases?** Unknown

**At what distance from the cap/seal is the nearest domestic structure located?** None

**At what distance from the cap/seal is the nearest domestic drinking water source?** None

### **Summary of emergency response factors**

None

### **Summary hazard ranking system factors**

None

### **Summary of reclamation factors**

Unknown

## Part VI Photos



Photo 1. Direction down towards the site



Photo 2. Washed out path leading to the site



Photo 3. Washed out path leading towards the site

**Part VII      Contacts Reports and Information**Name: Stanley Edison (928) 871-6861Eugene Esplain (928) 871-7331Title or official role (if any) Navajo EPA Superfund ProgramAddress PO Box 2946, Window Rock, AZ 86515Information provided Lead Regulatory Agency

Name\_\_\_\_\_

Title or official role (if any) \_\_\_\_\_

Address\_\_\_\_\_

Telephone number\_\_\_\_\_

Information provided\_\_\_\_\_

Name\_\_\_\_\_

Title or official role (if any) \_\_\_\_\_

Telephone number\_\_\_\_\_

Information provided\_\_\_\_\_


Name\_\_\_\_\_

Title or official role (if any) \_\_\_\_\_

Telephone number\_\_\_\_\_

Information provided\_\_\_\_\_

Figure 1 - Gamma Radiation Measurements, Above Two Times Background  
Tommy James (203)  
Round Rock Chapter, Navajo Nation, Arizona



#### Legend

##### Gamma Radiation Measurements

- < 2X Background
- > 2X Background

Gamma survey conducted 10/2009  
Measured as counts per minute (cpm)

Average background = 8,250 cpm

- ▨ Inaccessible due to steep grades
- General Direction Down-Slope
- Mine Claim Boundaries

0 150 Feet



**WESTON**  
SOLUTIONS

**Figure 2 - Gamma Radiation Measurements**  
**Tommy James (203)**  
**Round Rock Chapter, Navajo Nation, Arizona**



### Legend

#### Gamma Radiation Measurements

- 0 - 10,000
- 10,000 - 15,000
- 15,000 - 20,000
- 20,000 - 50,000
- 50,000 - 100,000
- > 100,000

■ Inaccessible due to steep grades

→ General Direction Down-Slope

■ Mine Claim Boundaries

Gamma survey conducted 10/2009  
Measured as counts per minute (cpm)

Average background = 8,250 cpm



0 150 Feet



**WESTON**  
SOLUTIONS